



# Superb

## Sealer / Finisher

**BRINGS OUT THE HIDDEN BEAUTY OF YOUR FLOORS**

Slip Resistance, Self Leveling,  
Non-Yellowing & Non-Powdering



### **STORAGE & DISPOSAL**

**Storage:** Store in a well-ventilated place. Keep cool.

**Disposal:** Dispose of contents/container in accordance with licensed collector's sorting instructions.

**Superb** maintains its beautiful high gloss with minimal maintenance time.

**Superb** will keep its radiant gloss, regardless of the maintenance program, equipment, or timetable you're working with.

**Superb** is versatile, can be used on resilient and hard floor surfaces such as vinyl, rubber, asphalt, vinyl composition tile, terrazzo, slate, marble, concrete and quarry tile.

**Superb** has self leveling coats that are easy to apply and dries rapidly.

**Superb** helps reduce the money spent to repair streaked floors and the need for designated floor crews.

**Superb** is non-yellowing which lengthens time between stripping intervals and reduces recoat/cuts labor costs.

**Superb**'s non-powdering floor sealer/ finish stays intact to last longer and reduces recoats labor costs.


**Superb** is extremely durable so will hold up under extreme conditions.

**Superb** has excellent slip resistance, providing a shiny, but safe walking surface.

**Superb** does not require buffering, but if desired it can be buffed at any speed.

**Superb** holds up to repeated scrubbing with its detergent resistance making the coats last longer between applications.

**Superb** resists against scuffs and black marks to preserve your floors beauty for long lasting results.



## Suberb

### Technical Specifications

pH	8.2 - 8.6
Weight/Liter	1 kg
Leveling	Excellent
Film Colour	Water Clear
Removability	Excellent
Drying Time	30 Minutes
Black Mark Resistance	Excellent
Freeze-Thaw Stability	Pass 3 Cycles
Scrubability	Excellent
Slip Index ASTM 2047	0.60 Excellent

### DIRECTIONS

#### Floor Preparation:

1. Strip floor thoroughly using a recommended floor stripper according to directions.
2. Pick up spent solution with mop or wet vacuum as soon as each floor section has been stripped. Do not allow solution to dry.
3. Rinse floor thoroughly with clear water. Changing rinse water frequently to prevent redepositing of dirt and stripper residue.
4. Allow floor to dry thoroughly before applying **Suberb**.

#### Application:

1. Use a clean finish mop and clean bucket reserved only for floor finish application.
2. Saturate mop thoroughly, press firmly into wringer to remove excess finish. Do not wring mop.
3. Apply **Suberb**. Excellent results are obtained by applying even coats.
4. Allow each coat to dry thoroughly, usually 30 minutes under normal humidity conditions.

#### Maintenance:

1. Dust mop floor.
2. Damp mop or auto scrub as required using **PH 7**, **Synthetic Lemon**, **Netra Pine** or **Low Foam 7** Neutral Floor Cleaners.
3. If desired, spray buff as needed.

### AVAILABLE SIZES



4L



10L